

CRITICAL DESIGN REVIEW FOR THE WELDS OF PORT TUBES ON MONOLITH VESSEL

F. Sordo¹, on behalf of ESS-Bilbao team, AVS and Cadinox teams.

Consorcio ESS-BILBAO, AVS and CADINOX

March 15th, 2021

A (1) A (1) A (1) A

March 15th, 2021

1 / 18

Table of contents

Introduction

3



- Intermediate metrology
- Pressure and vacuum test
- 5 Machining of the windows
- 6 Vessel instability
 - 7 Final tolerances



- 21

イロト イポト イヨト イヨト

ESS Monoltih Vessel on ESS target station



CDR-WL (ESS-BILBAO)

Redesign work

Contract awarded to AVS+CADINOX

On September 2018, the manufacturing contract was awarded to AVS+CADINOX. The new manufacturing team adapted the manufacturing plan to his technical capacities and split the vessel in two sections connected in a flange.

CADINOX vertical lathe. Maximum hight \sim 3 m



Bolted connection

+ sealing weld on site

A

Redesign work

Contract awarded to AVS+CADINOX

On September 2018, the manufacturing contract was awarded to AVS+CADINOX. The new manufacturing team adapted the manufacturing plan to his technical capacities and split the vessel in two sections connected in a flange.

CADINOX vertical lathe. Maximum hight \sim 3 m



Redesign work

AVS+CADINOX changes requested

The thickness of the flanges and lateral walls were increased to withstand the loads produced in the machining process. The connection between both sections relies on bolted flange seal welded on site.

Buckling analysis. Safety factor > 4



э

Monolith Vessel: Remarks

Combination of submerged arc and TIG

The combination of RCC-MRx manufacturing rules for 316L and the vacuum requirements limit the welding options. The solution selected was to combine submerged arc (121) and semiautomatic TIG (141) in most of the welding lines.

Example of welding strategy for monolith vessel



Monolith Vessel: Remarks

Thicknesses from 25 to 90 mm

The thickness of the vessel during the welding is related with the needs in the final machined areas. The frame for the windows only covers the windows area.



Manufacturing 18-11-2019 to 20-10-2020



Lower part body assembled by tack welding





Manufacturing 18-11-2019 to 20-10-2020





Manufacturing 18-11-2019 to 20-10-2020



CDR-WL (ESS-BILBAO)

8 / 18

Manufacturing 18-11-2019 to 20-10-2020





Manufacturing 18-11-2019 to 20-10-2020



Lower part already out of positioner

Inside surface view



Metrology intermediate control steps

The intermediate metrology shows deformations above the expected values in the windows frame. However, there is still large amount of extra material for final machining.

Dimensional control previous to pressure test (Mar 6th, 2020)



Cilindro soladura Lectures: 108							
		real	nominal	Desv	- tol.	+tol.	FueraTol
Diámetro		5.390,943mm			-0.050mm	0,050mm	
Cilindricidad	N	15.079mm		15,079mm	0.000mm	0.050mm	15.029mm

Cilindro							Lectures:80
		real	nominal	Desv	- tol.	+tol.	FueraTol
Diámetro		5.396,545mm			-0.050mm	0.050mm	
Cilindricidad	N	16,547mm		16,547mm	0.000mm	0,050mm	16,497mm

Pressure completed

Pressure test completed without incidences. Pre and post test metrology shows only elastic deformation during the test as it was expected.

Pressure test completed on April 29th, 2020



Pressure and vacuum test completed

Vacuum level completed. Values measured almost a factor of 10 better than the acceptance criteria for leaks and vacuum level.

Vacuum test completed May 15th, 2020

DEW POINT RESULTS	Value	Units
Dew Point must be lower than	-40,0	۹C
Dew Point Temperature	-53,9	۰C
PRESSURE RESULTS	Value	Units
Pressure must be lower than	1,0E-05	mbar
Pressure	1,0E-06	mbar
LEAK TEST RESULTS	Value	Units
Leak tightness requirement must be lower than	2,00E-08	mbar I s ⁻¹
Leak evaluation	6,57E-09	mbar I s ⁻¹
PRESSURE RISE TEST RESULTS	Value	Units
Slope Differential must be lower than	10%	mbar I s ⁻¹
Initial Pressure Rise Slope	1,34E-03	mbar I s ⁻¹
Final Pressure Rise Slope	1,30E-03	mbar I s ⁻¹
Differential Pressure Rise	0,004%	mbar i s ⁻¹

◆□▶ ◆□▶ ◆ □▶ ◆ □▶ ● □ ● ● ● ●

Machining of the windows restarted in June 2020

After several clarification work in the functional tolerances of the windows the machine work restarted on June 2020. On August 4^th , 2020 the manufactured reported "instability in the vessel". The machining velocity was reduced to 1/3 of the previous speed.

Inspection visits on July 2020.



Machining of the windows restarted in July 2020

After several clarification work in the functional tolerances of the windows the machine work restarted on July 2020. On August 4^th , 2020 the manufactured reported "instability in the vessel". The machining velocity was reduced to 1/3 of the previous speed.

Inspection visits on July 2020.



Strategy to achieve window tolerances

The manufacturer selected a two step machining approach (after the premachining):

- 1st stage from 3 mm to 1.5 mm.
- 2nd from 1.5 mm to 0.5 mm (finished before August closure)

Window to focal point



Strategy to achieve window tolerances

After the 15 days August closure, the manufactured reported changes in the geometry compared with dimensional control performed after the 2^{nd} machining step.

August 28^t h dimensional control



Strategy to achieve window tolerances

After the 15 days August closure, the manufactured reported changes in the geometry compared with dimensional control performed after the 2^{nd} machining step.

August 28^t h dimensional control



15 / 18

Manufacturer report (I. Arrillaga August, 2021

- Completely unexpected distortion once material is removed from Windows. Pattern of "snake": out in the middle, inside in "1/4" and "3/4" and guite correct in extremities.
- Distance "L" cannot be respected is some Windows (highlighted in red)
- Distance "L" will be final machined to respect dimension in the rest of the Windows as planned (highlighted in green)
- Bottom surfaces and upper flange verified and no distortion.
- First and main hypothesis of root cause (TBC):
 - References and CAD-CAM machining program are correct
 - During 15 days, rested in the vertical lathe, unclumped. Possible "natural" stress relieve and distortion. Temperature range changing from 15°C-35°C.

March 15th, 2021

16 / 18

Final machining completion

The incidence was evaluated with ESS and the deviations in "L" distance can be compensated adjusting the length of the port tubes. The final tolerances of the vessel shows fluctuations in the position of the welding plane and good shape tolerances of the bevel lated to the center of the welding plane.

FAT metrology report



Final machining completion

The incidence was evaluated with ESS and the deviations in "L" distance can be compensated adjusting the length of the port tubes. The final tolerances of the vessel shows fluctuations in the position of the welding plane and good shape tolerances of the bevel lated to the center of the welding plane.

FAT metrology report



Conclusions

Main remark

- The manufacturing process of the vessel produces large residual stresses
- The vessel shows unexpected deformations during all the production processes (April 2021 metrology).
- The machining of the windows frames produces stress relaxations (~2-4 mm). This process was done in control conditions at low temperature and slow material removing. (June-August machining)
- After the windows machining, additional relaxation were produced (August 2021)
- Cadinox consider that additional distorsions of the vessel will be produced during the welding to the ports (> 3-5 mm)

- 31

18 / 18

March 15th, 2021