

# **Experience with machine protection system at J-PARC**

**N. Hayashi**

**October 11, 2022**

**ESS - J-PARC commissioning workshop**

# Contents


- MPS overview
  - MPS performance
  - A few samples of MPS failure
  - Summary
- 
- MPS: Machine Protection System
  - PPS: Personnel Protection System

# MPS overview


# MPS overview

- **MPS network**

- In Linac; MPS interlock signal flow from down- to up-stream
- MPS signal aggregation and transfer to Linac front-end through **CCR** to **stop beam**
  - Beam stop: all, MR-, MLF-inhibit
- MR/HD/NU MPS signal sent to **D3 building** and **abort beam**



# Machine Protection System



**Several kinds of interlock signal gathering:  
vacuum, LLRF, general, beam loss**

Conceptual  
Schematic design  
during construction era (2006)

February 24, 2006

ATAC 2006

J-PARC Control - 48


# MPS hardware for Linac/RCS

- **Linac/RCS**

- VME size chassis with original backplane
  - MPS signals transfer through bus or RS-422/RS-485
  - VME/DIO, CPU used to monitor status, control, to be an IOC
- (1) Standard module: 236
- (2) BLM module: 88
  - comparator function enable to change threshold



(1) Standard (2) BLM



(5-a) Front side of MPS chassis. 4 standard modules and 1 BLM module are installed.

# Present hardware (Linac/RCS)


- (3) E/O signal converter module: 16
  - Signal transfer for long distance; between buildings
- (4) Mask (& aggregation) module: 5
  - Signal aggregation and disable interlock logic depends on operational MODE
- (5) MPS chassis: 90
- + various “sub” system
  - Monitoring key magnet current, status of Liner motion device, beam destructive device...



(3) E/O (4) Mask

Connectors for E/O and mask module

Connectors for BLM module



Connectors for standard module

(5-b) Back side of MPS chassis. different type connectors are installed.

# Beam destinations


- A special application selects “**beam destination**” and advances state transition along certain sequences.
- **MPS** modifies interlock mask status according to “beam destinations”.
- **PPS** controls “Area”, where allowed region to deliver the beam. **PPS** also checks consistencies, modes and device status.
- “beam destination” transition **TEST** are performed just before beam operation starts.
  - All devices are ready to start beam.
  - It is easy to detect any defects and perform corrections (if necessary), before the scheduled beam operation.



# Beam power limiter


- **Beam Current integrator with appropriate timing gate**
- **One hour limiter**
  - “particle counter”
  - Required by PPS
- **One pulse limiter for MLF and MR**
  - Chopper (timing) failure caused too much beam
  - Since 2015
- **Vacuum window protection**
  - Zero degree beam dump (BD0) vacuum window broken within 6 seconds
  - Since 2018
- **FCT at 3-50 BT**
  - Monitoring numbers of particles for every pulse and one hour total

# Fast beam stop scheme



# MR inhibit scheme

- Fast beam stop by switching off RFQ RF
  - Ion Source Arc- and Extraction voltage shift
  - Continue MLF beam
- These logic realized by specially designed “Logic Controller”





# MPS performance


# MPS reaction time

- Linac BLM triggers stopping the beam

- BLM 21@Klystron gallery:  $\sim 10 \mu\text{s}$
- BLM55@L3BT via CCR:  $\sim 20 \mu\text{s}$



**BLM21 trigger!**



**BLM55W trigger!**

# New MPS project for Linac/RCS

construction phase in 2006  
Almost 15 years passed...

- **Requirements**

- **Module aging, parts obsolete, technology succession, ...**
- **More operational modes: Lack of flexibilities / signal lines**
- **compatibility: Old and New system have to be used for some time range**

- **New hardware**

- **Proto-type design started in 2018**
- **New modules and chassis was designed**
- **RCS: Standard modules already replaced**
- **BLM modules under design**

- **Linac**

- **First replacement has been done during this shutdown**
  - **Postponed for last year due to semi-conductor shortage and late delivery**



# Long term test

## <RCS MPS>

## <RCS New MPS>

- MPS signal from various places

*The same configuration as the present MPS is constructed for new MPS*



## **A few examples of failure events**



# Past malfunction events (1)

- **2011/3/11 Large Earthquake**


- Accelerator was half day maintenance mode

**9 months shutdown**

- **2013/5/23 HD incident**

- Cause: EQ magnet PS failure ... new beam abort system

**6 months shutdown**



- **2015/11/2 and later: Chopper malfunction**

- Fact: Twice intensive beam ( $8E+13$ ) than intended ( $4.3E+13$ )
- Cause: missing trigger pulse (due to O/E module)
- **1-shot MPS**: “num. of particles limiter for one pulse”

- **2016/2/25 vacuum chamber leak at MR abort beamline**

- Cause: noise stopped ramping up septum in the middle of cycle
- **ms-Abort** (immediate beam abort system) was introduced

- **2017/4/19 short power outage (~ 3 seconds)**

- Accelerator was half day maintenance mode
- Sudden power outage during operation has been studied?

## Past malfunction events (2)

- **2018/3/30 Small earthquake**

**Half day interruption**

- Many MPS and Linac FCT was broken, vacuum leak

- **2018/10/13 LI:BD0 vacuum window breakage**

- Without stopping beam, 25 Hz pulse beam hit the window after scraper removed.

- Countermeasure: num. of particles limiter with proper time constant

03:18:31 Beam destination change :LI BD30 → LI BD0


- At present only BD0 no other BD...

- **2019/9/11 15:39 Unplanned power outage**

- During summer shutdown, maintenance period


# Chopper malfunction

- **2015/11 (November, 2015) and sometimes**
  - **Fact:** Twice intensive beam ( $8E+13$ ) than intended ( $4.3E+13$ )
  - **Cause:** missing trigger pulse (due to O/E module)
  - **1-shot MPS:** “num. of particles limiter for one pulse”
- **2016/6/29 (29 June, 2016)**
  - **Beam current pattern by CT**
    - Normal (up) , MPS event (down)
  - Normally the pattern is exact comb shape
  - MPS events shows some residual beam
    - It is due to chopper malfunction
  - No beam loss in the linac
  - But heavy beam loss in the RCS
  - Root cause is timing module problem




# L3BT: Beam window destruction


- The beam window before the 0deg beam dump was broken by **unexpected high intensity beam** on Oct. 13<sup>th</sup>, 2018.



**Beam window (0.36mm Ni)**  
To separate vacuum  $10^{-7}$  and  $10$  pa



Hole  
Observation of the failed beam window





(Oct. 13<sup>th</sup>, 2018)

**Beam stop:**  
500us -> 100us, 25Hz -> 2.5Hz

Beam stop <- "Skip"  
(Human error)

**Destruction**  
(estimated temp.:  
~1,500°C after 1s)



# L3BT: Beam window destruction

- **Date**

- October 13, 2018, 07:15 **LI: beam tuning**

- **Event description**

- **MPS: Bad vacuum at zero degree Beam Dump (BD0)**

**Stopped by bad vacuum  
Not by BLM!**

- **Impact / consequence**

- **Nine hours lost** to figure it out. BD0 was forbidden for a few months.
- **Beam window was broken. Replaced in the end of year with grate care**

- **Root cause**

- **Full beam (50mA, 500us, 25Hz) irradiated the window for six seconds**
- **Human error (?) (not following ordinary procedure)**
- **(BLM threshold was appropriate level...?)**

- **Countermeasure / preventing system**

- **One second integral num. of particle limiter**

# Summary

- **J-PARC MPS hardware and scheme presented**
  - **Beam power limiter**
  - **Beam stop/inhibit scheme**
  - **Upgrade status reported**
- **Some MPS examples**
  - **MPS performance: response speed**
  - **A few examples of failure events**